



ÉCROUS BORGNES



| d | a | H | h |
|-------|-----|------|-----|
| M 3 | 5,5 | 5,1 | 2,4 |
| M 4 | 7 | 6,7 | 3,2 |
| M 5 | 8 | 8 | 4 |
| M 6 | 10 | 10 | 5 |
| M 8 | 13 | 13 | 6,5 |
| M10 | 16 | 16,5 | 8 |
| M12 | 18 | 19,5 | 10 |
| (M14) | 21 | 22 | 11 |
| M16 | 24 | 25 | 13 |
| M20 | 30 | 31 | 16 |
| M24 | 36 | 37 | 19 |
| M30 | 46 | 47 | 24 |
| M36 | 55 | 56 | 29 |
| M42 | 65 | 66 | 34 |
| M48 | 75 | 75 | 38 |